

Work Order ID 96525

96525

Page 1

Tuesday, January 29, 2013 11:08:06 AM

Item ID: D135-819-011 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Dual Disabling
 Start Date: 1/29/2013 Start Qty: 1.00 ***1*** Cust Item ID:
 Required Date: 1/29/2013 Req'd Qty: 1.00 ***1*** Customer:
 Reference: DISSASSEMBLE

Approvals: Process Plan: MF Date: 13-1-29 Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN-D135-819	A								

150 0.00

150

Packaging Memo 0.00
 Packaging PULL FROM STOCK D135-819-011 B 80891 X 1

REMOVE D3393-041 X 1 B 79036
 D4571-041 X 1 B 80892

AND PUT BACK IN STOCK UNDER ORIGINAL BATCH NUMBER

MF- 13-1-29

160 QC21- Final Inspection - Work Order Release 0.00

160

QC Memo 0.00
 Quality Control

CH6001

13/1/29

MF

13-1-29

Picklist Print

Tuesday, January 29, 2013 11:08:05 AM

Page 1

Work Order ID: 96525

Parent Item: D135-819-011

Parent Item Name: Dual Disabling

Start Date: 1/29/2013

Required Date: 1/29/2013

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP REV:A 12.01.06 NEW ISSUE DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D135-819-011 Dual Disabling		Manufactured	No				Each	3.0000		1			
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				FG128		3							
				80891		3							
D3393-041 Battery Lock Assembly		Manufactured	No				Each	3.0000		-1			
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST486		3							
				84316		1							
				96377		2							
D4571-041 Tail Rotor Disabling		Manufactured	No				Each	0.0000					

IX 80891 MF
13-1-29

79036 MF
13-1-29

80892

13-1-29